

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AT238
SSE
1/4-1/2
0.354 mi.
1871 ft.
VAULT 1532
WEST 8TH ST/SURF AV
BROOKLYN, NY
Site 9 of 10 in cluster AT

NY Spills **S106014151**
N/A

Relative:
Higher

Actual:
3 ft.

SPILLS:

Name: VAULT 1532
Address: WEST 8TH ST/SURF AV
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0301735 / 2003-06-17
Facility ID: 0301735
Facility Type: ER
DER Facility ID: 141588
Site ID: 168064
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2003-05-18
Investigator: KMFOLEY
Referred To: Not reported
Reported to Dept: 2003-05-18
CID: 211
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-05-18
Spill Record Last Update: 2003-06-17
Spiller Name: LARRY COSTA
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: LARRY COSTA
DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY Con Ed e2mis #148402: 5/18/03 12:15 HRS. E. WORRELL #08452, TROUBLESHOOTER HV WITH #9, REPORTS ON LOCATION RESPONDING TO STEAMING TRANSFORMER AND WHILE PUMPING WATER OUT OF VS-1532 AT 12:10 HRS.

FOUND TRANSFORMER LEAKING. CURRENTLY THERE IS APPROX. 2 PINTS TRANSFORMER OIL ON APPROX. 200 GAL. WATER. NO OIL WAS PUMPED ONTO STREET. VAULT HAS A SUMP PUMP, BUT IT IS DISCONNECTED. SPILL APPEARS TO BE CONTAINED. ENV. STOP TAG #04297 WILL BE PLACED. NOT SAFE TO TAKE A SAMPLE AT THIS TIME. #9 REMAINS ON LOCATION. NETWORKS WILL BE NOTIFIED AND WILL NEED TO TAKE AN OIL SAMPLE FROM THE TRANSFORMER. 24-HR DEMINIMIS. FEEDER REMAINS IN SERVICE. AS PER SHIFT MANAGER, CLEANUP PENDING UPDATE FROM NETWORKS. Transformer Info from ECC Warehouse: Serial # NCV76680102, Mfr: WE, Mfr. Date: 8/23/1991, Install Date: 3/25/1993, PCB Sample Dated 1/15/1997: 9 PPM. update @ 1618 hrs 5/18 remove incident from 24 hour program transformer to be replaced. thorngran networks claims unit has 4 pounds of pressure from leaking secondary bushing. leak stopped once fdr removed from service. transformer to be replaced. Update - 5/19/03 0400hrs T. Fernandez OS env. ops reports removed all liquids with over 50 tanker. Pushed all dirt to side and made access for netw to valve to

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Remarks:

take oil sample from unit. Sample taken from unit and brought to chemlab by tanker driver. Unit could not be drained at this time until all grounds were placed on fdr. No parking on Monday 9am - 1030hrs. UPDATE @ 0815 HRS 5/19 LAB RESULTS RECEIVED SEQ #03-04140-001 @ 2PPM PCB. 6/3/03=1325HRS MERCADO ENVIR OPPS REPORTS INTIAL CLEANUP DONE . STRUCTURE MAKES WATER.ENVIR TAG REMAINS PENDING REPLACEMENT OF UNIT. 6/4/03 16:45 HRS. -- R. VEGA OF BROOKLYN ENV. OPS. REPORTS HE AND ESPONDA COMPLETED CLEANUP: STRUCTURE DOUBLE-WASHED WITH BIOGEN 760, SUMP WAS FOUND ALREADY SEALED AND ENV. STOP TAG #04297 WAS REMOVED. 6/5/03 04:55 HRS PER FDR REP THE UNIT WAS REPLACED "

"2 PINTS TRANSFORMER OIL ON 200 GALS OF WATER - ACTIVE LEAK FROM SECONDARY BUSHING - SPILL IS CONTAINED - CLEAN UP PENDING REMOVAL OF TRANSFORMER - HX PCB COUNT 9PPM - CON ED 148402"

All Materials:

Site ID: 168064
Operable Unit ID: 869757
Operable Unit: 01
Material ID: 506222
Material Code: 0020A
Material Name: transformer oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported